

Hyundai Accent Hatchback
MY 2012
Page 2 of 2

TA must be hinged up, put through slot in mat
Similar to Hyundai Veloster, MY 2012



Above: Owner must hinge the TA upward before returning the mat to proper position.



Left: When TA is threaded through the slot in the mat, it's obvious and easy to use.